

Revised Terms of Reference [28/11/2000]

Heavily Modified Waters in Europe Case Study on the Seefelder Aach River -Draft-

Markus Funke

Dietrich Borchardt

Michaela Frey

Ingrid Schleiter

Kerstin Geffers

Institute of Water Resources Research and Management

University of Kassel

Kurt-Wolters-Str. 3 - G-34125 Kassel

Phone:+49-(0)561-8043912, Fax:+49-(0)561-8043642

E-mail: funkem@hrz.uni-kassel.de

| Table of Contents | | page |
|------------------------|---|--------------------|
| <u>PART I</u> | | 5 |
| 1 | Preface | 6 |
| 2 | Summary Table | 7 |
| 3 | Introduction | 9 |
| 3.1 | Choice of Case Study | 9 |
| 3.2 | General Remarks | 9 |
| 4 | Description of Case Study Area | 12 |
| 4.1 | Geology, Topography and Hydrology | 12 |
| 4.2 | Socio-Economic Geography and Human Activities in the Catchment | 14 |
| 4.3 | Identification of Water Bodies | 14 |
| 4.4 | Discussion and Conclusions | 15 |
| <u>PART II</u> | | 16 |
| 5 | Physical Alterations | 17 |
| 5.1 | Pressures and Uses | 17 |
| 5.2 | Physical Alterations | 23 |
| 5.3 | Changes in the Hydromorphological Characteristics of the Water Bodies and Assessment of Resulting Impacts | 27 |
| 5.4 | Discussion and Conclusions | 27 |
| 6 | Ecological Status | 28 |
| 6.2 | Physico-Chemical Elements | 33 |
| 6.3 | Definition of Current Ecological Status | <u>3635</u> |
| 6.4 | Discussion and Conclusions | <u>3837</u> |
| 7 | Identification and Designation of Water Bodies as Heavily Modified | <u>4039</u> |
| 7.1 | Provisional identification of HMWB | <u>4039</u> |
| 7.2 | Necessary Hydro-morphological Changes to Achieve Good Ecological Status | 41 |
| 7.2.1 | Required hydro-morphological changes and required measures to achieve the Good Ecological Status | 43 |
| 7.2.2 | Impacts on water uses and significant adverse effects | 45 |
| 7.2.3 | Impacts on the wider environment | 46 |
| 7.3 | Assessment of Other Environmental Options | 46 |
| 7.3.1 | Identification and definition of the beneficial objectives served by the modified characteristics of the water body | 46 |
| 7.3.2 | Alternatives to the existing "water use" | 47 |
| 7.4 | Designation of Heavily Modified Water Bodies | 48 |
| 7.5 | Discussion and Conclusions | 49 |
| <u>PART III</u> | | 50 |
| 10 | Conclusions, Options and Recommendations | 51 |
| 10.1 | Conclusions | 51 |
| 10.1.1 | Identification of water bodies, scaling | 51 |
| 10.1.2 | Reference conditions | 51 |
| 10.1.3 | Definition of MEP and GEP | 51 |
| 10.1.4 | Significant pressures / significance criteria | 53 |
| 10.1.5 | Quality elements | 53 |

| | | |
|--------|---|-----------|
| 10.1.6 | Designation as HMWB oder minor objectives | 53 |
| 10.1.7 | Relation of HMWB and natural waters | 54 |
| 10.2 | Options and Recommendations | 54 |
| 11 | Bibliography | 56 |
| 12 | List of Annexes | 58 |

List of Tables

| | | |
|---------------------|---|-----------|
| Table 2.1: | Summary Table | 7 |
| Table 4.3.1: | Description of the Seefelder Aach basin | 14 |
| Table 5.1.1: | Assessment and classification of the resulting impacts | 18 |
| Table 5.1.2: | Criteria for the identification of significant pressures | 19 |
| Table 5.1.3: | Specification of significant pressures in the case study | 22 |
| Table 6.1.1: | Fish population | 32 |
| Table 6.2.1: | Load at the gauging station Uhldingen 1997 and 1998 | 33 |
| Table 6.3.1: | Transformation of the quality classes of the LAWA according to EU-WFD | 36 |
| Table 6.3.2: | Physico-chemical quality at the gauging station Uhldingen | 36 |
| Table 7.1.1: | Effects on the quality of morphological structure at the river caused by the pressure "Agriculture/Forestry" | 41 |
| Table 7.2.1: | Mitigation measures for the case study "Seefelder Aach" | 44 |
| Table 7.3.1: | Costs of alternatives (mitigation measures) [in €] | 48 |
| Table 10.1.3: | Maximum and Good Ecological Potential for Heavily Modified Waterbodies | 52 |

List of Figures

| | | |
|---------------|---|----|
| Figure 3.2.1: | Location of the Seefelder Aach catchment | 9 |
| Figure 3.2.2: | Topography of the Seefelder Aach basin | 10 |
| Figure 4.1.1: | River network | 13 |
| Figure 5.2.1: | Overall-evaluation | 23 |
| Figure 5.2.2: | Morphological status (without urban sections) | 24 |
| Figure 5.2.3: | Longitudinal profile | 24 |
| Figure 5.2.4: | Weirs with a high \geq 30 cm | 25 |
| Figure 5.2.5: | Land area in the Seefelder Aach catchment | 26 |